



Quote - AMASOQ10217

Amaya Industries
Address: Alrode Multipark, JG Strijdom Road, South Block, Alrode, Alberton, Gauteng, 1450
Postal: Alrode Multipark, JG Strijdom Road, South Block, Alrode, Alberton, Gauteng, 1450
Contact Number: 0861500110
Email: info@amayaind.co.za
CO. Reg: 2008/160979/23
VAT No: 4760249377

CONTACT DETAILS

THARISA MINERALS
Stiaan Snyders
0711340174
SSnyders@tharisa.com
VAT No: 4860238387

ADDRESS

Portion 84 D/Kraal
Farm 342 JQ
Marikana
0284

LOCATION

Portion 84 D/Kraal
Farm 342 JQ
Marikana
0284

DETAILS

Date: 2026-06-11
Expiry Date: 2026-07-11
Customer Code: THA001
Reference: SERVICE
Sales Rep: Mampe Mosikidi

Code	Description	Qty	Unit Price	Disc %	VAT %	Excl Total	Incl Total
SERVICE	Comprehensive service on electronic key cabinet	1	26,775.68		15	26,775.68	30,792.03

Account Name: Amaya Industries CC
Bank: First National Bank
Account Number: 62191674962
Branch Code: 250655

Total Exclusive: R 26,775.68
Total VAT: R 4,016.35
Total: R 30,792.03

Att: The Buyer
CC: Stiaan Breeze Snyders
Cell: 071 134 0174
Email: SSnyders@tharisa.com

Service of 2 Cabinets at Tharisa Mine
25-07-KEY-7780 (40 key)
25-07-KEY-7960 (80 key)

Price Includes Per Cabinet:

- System diagnostic via the ecos Test Tool system diagnostic software.
- Test power supply voltage and ensure it is within acceptable range.
- Inspection of all locking solenoids.
- Adjust each locking solenoid to be in correct alignment with locking frame for accurate locking of ID-plugs.
- Thoroughly clean each locking solenoid for better operation and contact with ID-plugs.
- Earthing test on each locking nut on front keypad. Proper earth needs to be made with key panel to ensure good contact which is required to detect key removal and return.
- Check all ID-plug nose contact points for alignment and adjust where necessary. Out of alignment nose contact points will prevent proper contact with ID-plugs and will result in failed key removal / return reading.
- Remove all ID-plugs and clean thoroughly. Clean ID-plugs will ensure proper contact with contact nose.
- Firmware upgrade on all hardware components.
- Replace Back-up Batteries- 1 battery per cabinet
- Software upgrade which includes bug fixes.
- Check all system relevant components which includes: Mainboard, Processor, Keyboards, Olimex, Versa, Atmels, Secure board, Card reader, Fingerprint reader, Keypad, Touch Screen, LCD.
- Tighten all screws, nuts & bolts securing components to the cabinet housing.
- Check and adjust door hinges to ensure properly alignment to door lock.
- Test and clean door lock and ensure that door lock correctly without any wear from the door latch. Adjust door latch if necessary
- Thoroughly clean complete cabinet housing inside and outside.
- Testing full communication between systems and the server

Price Excludes:

- Any additional repair/parts needed – a separate quote will be sent.